

Appendix B: Photographs



Figure 1: View of the crossing over the Sand River that washed away during the flood event in 2012.



Figure 2: View of the temporary structure that is currently in place along the deviation allowing flow in the Sand River.



Figure 3: View of the current bypass and crossing over the Sand River.



Figure 4: View of the undermined structure that requires replacement.



Figure 5: Upstream view of Sand River crossing.



Figure 6: Downstream view of the Sand River crossing.